



Verifying MS12 Output Lead Connection

Verifying Output Lead Connection

Put connector in to mating adapter, ensure the key is properly aligned. Red arrow shows position of the key.



Verifying Output Lead Connection

Tighten the connector. If the key was aligned properly, it should look like the picture on the left.

